



**ALUMINUM BODY**

**NOTE**  
 DIMENSIONS SHOWN ARE APPROXIMATE AND ARE SUBJECT TO MINOR DEVIATIONS AS MAY OCCUR OR BE NECESSARY IN CONSTRUCTION. MINOR DETAILS NOT SHOWN.

1. WHEEL CHOCKS AND MOUNTING BRACKETS PROVIDED BY CUSTOMER
2. AIR INLET/OUTLET MILTON D FEMALE FITTING AT DRIVER'S SIDE PUMP PANEL
3. REMOTE AIR TANK DRAIN LOCATED UNDER COMPARTMENT LS3
4. BATTERY CHARGER LOCATED BEHIND DRIVER'S SEAT
5. BATTERY CHARGER INDICATOR LOCATED ON DRIVER'S SEAT RISER
6. SUB FEED BREAKER BOX LOCATED BEHIND DRIVER'S SEAT
7. DUAL L.E.D. LIGHT STRIPS LOCATED BELOW HOSE BED COVER
8. DRIP PAN GUARD FOR ROLL-UP DOOR LOCATED ON ALL COMPARTMENTS WITH ROLL UP DOORS
9. DUAL L.E.D. LIGHT STRIPS ON EACH SIDE OF ALL COMPARTMENTS WITH ROLL UP DOORS
10. L.E.D. LIGHT STRIPS IN HATCH COMPARTMENTS
11. ONE FULL WIDTH/DEPTH ADJUSTABLE SHELF IN COMPARTMENTS LS2, LS3, AND RS1; THREE IN LS1
12. ONE SLIDE-OUT ADJUSTABLE TRAY IN COMPARTMENT LS3
13. CHROME RELEASE LATCH WITH SINGLE HAND OPERATION FOR TRAY IN COMPARTMENTS RS1 AND RS2
14. ONE TILT/SLIDE-OUT ADJUSTABLE TRAY IN COMPARTMENTS RS1 AND RS2
15. ONE FLOOR MOUNTED SLIDE-OUT FULL WIDTH/FULL DEPTH TRAY IN COMPARTMENTS LS1, LS3, AND RS1 ONLY W/LOCK
16. ONE FLOOR MOUNTED SLIDE-OUT TRAY IN COMPARTMENT B1
17. TWO SLIDE-OUT ALUMINUM TOOL BOARDS IN COMPARTMENT RS3
18. PARTITION BETWEEN COMPARTMENTS LS1/RS1 AND RS1/B1
19. ONE VERTICAL DIVIDER IN HATCH COMPARTMENT LH2 REAR OF INVERTER LOCATION
20. XANTREX INVERTER LOCATED IN HATCH COMPARTMENT LH2
21. ONE 120V DUPLEX RECEPTACLE STRIP LOCATED IN LS1 AND RS1
22. ONE 120V WEATHERPROOF RECEPTACLE LOCATED IN CARGO AREA

		JOB NO.	36417
		SCALE	DATE
<b>TITLE</b> 1500-D-525P, 500G WATER W/25G FOAM, 152" BODY (2) SPEEDLAYS, DELUGE, HUSKY 12 FOAM SYSTEM		DRAWN BY	31AUG21
<b>FOR</b> DENTON FIRE DEPARTMENT DENTON, TEXAS		CHECKED BY	31AUG21
<b>DWG NO.</b> 36417AD		SHEET SIZE	SHEET NO.
		D	1 OF 1

REV	DATE	BY	CH	ENFORCER
27DEC21		SAM	COS	
18NOV21		SAM	COS	
03SEP21		SAM	EGO	